ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	10	Dodda Bommasandra
Street ID	**Street Name**	**Significant Landmark**
W0178	NA	Houses
Segment No.	**Total Length (m)**	
10/S-W0178/S034106	359.50	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	359.50	77.558808	13.059983	77.555700	13.061112	Main Road	Cross Road

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to Roads and Drains at Doddabommasandra and Surrounding Area in Ward No. 10 (Doddabommasandra).	4000000	2019-20
Year	**Type of Work**	**Other Work Type**
2019 - 2020	Road	
Tender	**Work Details**	**Job No. / Work Code**
Tender	Construction of CC Road and CC Drain and Drain Development Work	010-20-000070
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/E-PMT/02 (42436)/WO/105/2020-21	11/09/2020	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
13/11/2020	12/11/2021	No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
K.V Subba Reddy		0.00
Phone No.	**E-Mail ID**	
9980915550		

Assistant Executive Engineer
Vidyaranyapura Sub Division
BBMP, Bangalore - 97

Field Inspection Details

Number of Trees	Any Other Information	Name
0		Swetha.N.R
Date of Inspection	**Remarks**	
30/01/2021		

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	Sri.S.P.Ranganath	30/01/2021	01/03/2021	As proposed
SE	Vijay Kumar Haridas	30/01/2021	01/03/2021	Forwarded
EE	Mohandas H T	30/01/2021	01/03/2021	Verified
AEE	Shivakumar M Goudar	30/01/2021	01/03/2021	Verified
AE	Swetha N.R	30/01/2021	01/03/2021	Mobile Verification Done
AE	Swetha N R	30/01/2021	01/03/2021	Foward

Assistant Executive Engineer
Vidyaranyapura Sub Division
BBMP, Bangalore - 97

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	10	Dodda Bommasandra
Street ID	**Street Name**	**Significant Landmark**
W0247	4th Crs	Houses
Segment No.	**Total Length (m)**	
10/S-W0247/S033317	276.82	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	276.82	77.558008	13.062372	77.557146	13.060587	Venugopalswamy Temple Road	Cross Road

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to Roads and Drains at Doddabommasandra and Surrounding Area in Ward No. 10 (Doddabommasandra).	4000000	2019-20
Year	**Type of Work**	**Other Work Type**
2019 - 2020	Road	
Tender	**Work Details**	**Job No. / Work Code**
Tender	Construction of CC Road and CC Drain and Drain Development Work	010-20-000070
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/E-PMT/02 (42436)/WO/105/2020-21	11/09/2020	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
13/11/2020	12/11/2021	No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
K.V Subba Reddy		0.00
Phone No.	**E-Mail ID**	
9980915550		

Assistant Executive Engineer
Vidyaranyapura Sub Division
BBMP, Bangalore - 97

Field Inspection Details

Number of Trees	Any Other Information	Name
0		Swetha.N.R

Date of Inspection	Remarks
30/01/2021	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	Sri.S.P.Ranganath	30/01/2021	01/03/2021	As proposed
SE	Vijay Kumar Haridas	30/01/2021	01/03/2021	Forwarded
EE	Mohandas H T	30/01/2021	01/03/2021	Verified
AEE	Shivakumar M Goudar	30/01/2021	01/03/2021	Verified
AE	Swetha.N.R	30/01/2021	01/03/2021	Mobile Verification Done
AE	Swetha N R	30/01/2021	01/03/2021	Forward

Assistant Executive Engineer
Vidyaranyapura Sub Division
BBMP, Bangalore - 97

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mananagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	10	Dodda Bommasandra
Street ID	**Street Name**	**Significant Landmark**
W0227	NA	Houses
Segment No.	**Total Length (m)**	
10/S-W0227/S033836	124.92	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	124.92	77.555897	13.061033	77.555924	13.062162	Main Road	Cross Road

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to Roads and Drains at Doddabommasandra and Surrounding Area in Ward No. 10 (Doddabommasandra).	4000000	2019-20
Year	**Type of Work**	**Other Work Type**
2019 - 2020	Road	
Tender	**Work Details**	**Job No. / Work Code**
Tender	Construction of CC Road and CC Drain and Drain Development Work	010-20-000070
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/E-PMT/02 (42436)/WO/105/2020-21	11/09/2020	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
13/11/2020	12/11/2021	No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
K.V Subba Reddy		0.00
Phone No.	**E-Mail ID**	
9980915550		

Assistant Executive Engineer
Vidyaranyapura Sub Division
BBMP, Bangalore - 97

Field Inspection Details

Number of Trees	Any Other Information	Name
0		Swetha.N.R
Date of Inspection	**Remarks**	
30/01/2021		

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	Sri.S.P.Ranganath	30/01/2021	01/03/2021	As proposed
SE	Vijay Kumar Haridas	30/01/2021	01/03/2021	Forwarded
EE	Mohandas H T	30/01/2021	01/03/2021	Verified
AEE	Shivakumar M Goudar	30/01/2021	01/03/2021	Verified
AE	Swetha.N.R	30/01/2021	01/03/2021	Mobile Verification Done
AE	Swetha N R	30/01/2021	01/03/2021	Forward

Assistant Executive Engineer
Vidyaranyapura Sub Division
BBMP, Bangalore - 97

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	10	Dodda Bommasandra
Street ID	**Street Name**	**Significant Landmark**
W0164	NA	Houses
Segment No.	**Total Length (m)**	
10/S-W0164/S033951	142.25	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	142.25	77.557236	13.062162	77.555924	13.062162	Cross Road	Cross Road

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to Roads and Drains at Doddabommasandra and Surrounding Area in Ward No. 10 (Doddabommasandra).	4000000	2019-20
Year	**Type of Work**	**Other Work Type**
2019 - 2020	Road	
Tender	**Work Details**	**Job No. / Work Code**
Tender	Construction of CC Road and CC Drain and Drain Development Work	010-20-000070
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/E-PMT/02 (42436)/WO/105/2020-21	11/09/2020	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
13/11/2020	12/11/2021	No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
K.V Subba Reddy		0.00
Phone No.	**E-Mail ID**	
9980915550		

Assistant Executive Engineer
Vidyaranyapura Sub Division
BBMP, Bangalore - 97

Field Inspection Details

Number of Trees	Any Other Information	Name
0		Swetha.N.R
Date of Inspection	**Remarks**	
30/01/2021		

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	Sri.S.P.Ranganath	30/01/2021	01/03/2021	As propposed
SE	Vijay Kumar Haridas	30/01/2021	01/03/2021	Forwarded
EE	Mohandas H T	30/01/2021	01/03/2021	Verified
AEE	Shivakumar M Goudar	30/01/2021	01/03/2021	Verified
AE	Swetha.N.R	30/01/2021	01/03/2021	Mobile Verification Done
AE	Swetha N R	30/01/2021	01/03/2021	Forward

Assistant Executive Engineer
Vidyaranyapura Sub Division
BBMP, Bangalore - 97